

**To:** Tim Benton (Tim.Benton@WestonSolutions.com)[Tim.Benton@WestonSolutions.com]  
**Cc:** Peter Lisichenko (lisichenko.peter@epa.gov)[lisichenko.peter@epa.gov]; Francisco Rodriguez[frodriguez@gesoncall.com]  
**From:** Daly, Eric  
**Sent:** Wed 2/22/2017 7:46:22 PM  
**Subject:** NFB- GNBC HVAC RTU  
[NFB GNBC HVAC Figure 02-22-2017.pdf](#)

Good Afternoon Tim:

Frank has been in discussion with Vastola Heating and they have encountered a problem with the return duct clearance above the drop ceiling. The duct that they had prefabbed for this unit per the drawings will not clear the center support beam for the office area. We are requesting the architect approval on relocating the return in the showroom space to the opposite side of the center beam.

I have attached a figure to better describe. Please request feedback from the architect and let us know if requires further information.

Thanks.

Regards,

Eric M. Daly  
On-Scene Coordinator/Radiological Response Specialist  
US Environmental Protection Agency- Region II

ERRD/RPB/PPS  
2890 Woodbridge Avenue  
Edison, NJ 08837  
[daly.eric@epa.gov](mailto:daly.eric@epa.gov)  
908-420-1707

"We must, indeed, all hang together, or assuredly we shall all hang separately", Benjamin Franklin